



Date
14/11/2019

Aircraft Status

G-CEOY

Type **Schweizer 269C-1**

Serial no **234**

NT Aviation

UK.145.01260 UK.MG.0632

Maintenance Program

MP/04444/P

Total time **2648**

Description of check or component	Check or repetitive AD			Component information							
	Check interval	Date or Hours at last compliance	Time Remaining	Part No	Serial no	Component life	Aircraft hours at install	Component hours at install	Date of install	Component Total time	Component time remaining
Airworthiness review Certificate	365	15/12/2018	30								
Fire Extinguisher	365	12/12/2018	27								
First Aid Kit	365	12/12/2018	27								
Engine 50 hr inspection	50	2639.4	41.4								
Engine 100 hr inspection	100	2639.4	91.4								
Engine 300 hr Inspection	300	2452.2	104.2								
Engine Overhaul	2000	2194.8	1546.8	HIO-360-G1A	L-32137-51A	2000	2194.8	0	10/06/2014	453.2	1546.8
Engine overhaul	4380	10/06/2014	2396	HIO-360-G1A	L-32137-51A	2000	2194.8	0	10/06/2014	453.2	1546.8
Main Transmission overhaul	4000	0	1352.0	269A5175-37	212	4000	0	0	13/01/2006	2648	1352
Tail Transmission Overhaul	4200	508.5	2060.5	269A5600-703	460	4200	508.5	0	15/02/2008	2139.5	2060.5



Date
14/11/2019

Aircraft Status

G-CEOY

Type **Schweizer 269C-1**

Serial no **234**

NT Aviation

UK.145.01260 UK.MG.0632

Maintenance Program

MP/04444/P

Total time **2648**

Description of check or component	Check or repetitive AD			Component information							
	Check interval	Date or Hours at last compliance	Time Remaining	Part No	Serial no	Component life	Aircraft hours at install	Component hours at install	Date of install	Component Total time	Component time remaining
Main Rotor Blade				269A1185-1	3201	5500	0	0	13/01/2006	2648	2852
Main Rotor Blade				269A1185-1	3202	5500	0	0	13/01/2006	2648	2852
Main Rotor Blade				269A1185-1	3203	5500	0	0	13/01/2006	2648	2852
Pitch Bearing Shaft				269A1240-7	6758	4000	1676.6	746.7	20/02/2012	1718.1	2281.9
Pitch Bearing Shaft				269A1240-7	6863	4000	0	0	13/01/2006	2648	1352
Pitch Bearing Shaft				269A1240-7	6844	4000	0	0	13/01/2006	2648	1352
Elastomeric Damper				269A1290-3	8415	6000	0	0	13/01/2006	2648	3352
Elastomeric Damper				269A1290-3	8412	6000	0	0	13/01/2006	2648	3352
Elastomeric Damper				269A1290-3	8416	6000	0	0	13/01/2006	2648	3352
Main Rotor Hub				269A5325-1	355	8000	0	0	13/01/2006	2648	5352



Date
14/11/2019

Aircraft Status

G-CEOY

Type **Schweizer 269C-1**

Serial no **234**

NT Aviation

UK.145.01260 UK.MG.0632

Maintenance Program

MP/04444/P

Total time **2648**

Description of check or component	Check or repetitive AD			Component information							
	Check interval	Date or Hours at last compliance	Time Remaining	Part No	Serial no	Component life	Aircraft hours at install	Component hours at install	Date of install	Component Total time	Component time remaining
Main Rotor Driveshaft				269A5326-1	205	4000	0	0	13/01/2006	2648	1352
Main Rotor Thrust Bearing				269A5050-63	4258	4000	0	0	13/01/2006	2648	1352
Main Rotor Transmission				269A5175-37	212	4000	0	0	13/01/2006	2648	1352
Main Transmission Pinion				269A5103-55	3407AGC	8000	0	0	13/01/2006	2648	5352
Main Transmission Ring Gear Carrier				269A5193.1	876	8000	0	0	13/01/2006	2648	5352
Main Rotor Mast				269A2010-15	169	13590	0	0	13/01/2006	2648	10942
Engine	300	2452.2	104.2	HIO-360-G1A	L-32137-51A	2000	2194.8	0	10/06/2014	453.2	1546.8
Magneto	500	2639.4	491.4	4347	14020067	2000	2194.8	0	10/06/2014	453.2	1546.8
Magneto	500	2639.4	491.4	4370	13120585	2000	2194.8	0	10/06/2014	453.2	1546.8
Fuel injector servo				2576586-1	70949405	2000	2194.8	0	10/06/2014	453.2	1546.8



Date
14/11/2019

Aircraft Status

G-CEOY

Type **Schweizer 269C-1**

NT Aviation

UK.145.01260 UK.MG.0632

Maintenance Program

MP/04444/P

Serial no **234**

Total time **2648**

Description of check or component	Check or repetitive AD			Component information							
	Check interval	Date or Hours at last compliance	Time Remaining	Part No	Serial no	Component life	Aircraft hours at install	Component hours at install	Date of install	Component Total time	Component time remaining
Fuel Pump				AF15473	05K806	2000	2194.8	0	10/06/2014	453.2	1546.8
Starter				149-24HT	F4C-221314	2000	2194.8	0	10/06/2014	453.2	1546.8
Upper Pulley Bearing				269A5050-78	Unknown	3000	0	0	13/01/2006	2648	352
Upper Pulley Bearing				269A5050-78	Unknown	3000	0	0	13/01/2006	2648	352
Idler Puller Bearing				269A5050-74	Unknown	3000	0	0	13/01/2006	2648	352
Idler Puller Bearing				269A5050-74	Unknown	3000	0	0	13/01/2006	2648	352
Lower Puller Bearing				269A5050-85	Unknown	3000	0	0	13/01/2006	2648	352
Lower Puller Bearing				269A5050-85	Unknown	3000	0	0	13/01/2006	2648	352
Lower Coupling Shaft	150	2603.3	105.3	269A5559-3	1670	6000	0	0	06/07/2018	2648	3352
Tailboom				269A2320-15	268	4200	0	0	13/01/2006	2648	1552



Date
14/11/2019

Aircraft Status

G-CEOY

Type **Schweizer 269C-1**

NT Aviation

UK.145.01260 UK.MG.0632

Maintenance Program

MP/04444/P

Serial no **234**

Total time **2648**

AD Number	SB Number	Description	Recurring?	Interval	Last Complied with	Next Due	Time Remaining	Notes
		FAA Ads						
99-04-14		Main Rotor Blade Abrasion Strip	Y	50				N/A to S/No
2000-16-05	C1B-009.1	Tail Rotor Swashplate	N					N/A C/W at Build
2005-10-12	C1B-017.1	Trim Actuator	N					N/A to S/No
2006-0171R1	L-168	Fuel Vent modification	N					N/A C/W at Build
2010-0219	C1B-028	Door Hinge Modification	N		30/11/2011			Modification
2011-12-16	C1B-032.1	Aft Cluster Mittings	N		30/11/2011			Modification
2015-23-01	C1B-036.1	TRDS Spline Fittings	Y	100	2639.4	2739.4	91.4	Inspection
2017-14-06	C1B-043A	Lower Coupling Shaft MPI	Y	150	2603.3	2753.30	105	Inspection
2005-0023R3	SB388	Avalve wear inspection	Y	300	2480.8	2780.8	132.8	Inspection
2011-26-04		Fuel Injector Lines	Y	100	2639.4	2739.4	91.4	Inspection
76-07-12		Bendix Ignition Switches	Y	100	2639.4	2739.4	91.4	Function Check



Date
14/11/2019

Aircraft Status

G-CEOY

Type **Schweizer 269C-1**

NT Aviation

UK.145.01260 UK.MG.0632

Maintenance Program

MP/04444/P

Serial no **234**

Total time **2648**

AD Number	SB Number	Description	Recurring?	Interval	Last Complied with	Next Due	Time Remaining	Notes
		SBS						
	C1B-001-017.1							N/A Complied with at Build
	C1B-018.1	Modification of Locknut/Hoist Eye Assembly						N/A to S/No
	C1B-019.1	Tail Rotor Swashplate Bellcrank Assembly Safety Washer Installation		N	30/03/2007			Inspected
	C1B-020	Slick Service Bulletin SB1-06A		N	30/03/2007			Inspected
	C1B-021.1	Main Transmission Input Pinion Corrosion Protection		N	16/06/2019			Found complied with
	C1B-022.1	Tail Rotor Drive Shaft Splined Fittings Inspection		N	30/11/2011			Inspected
	C1B-023	Reprint of Precision Airmotive Mandatory Service Bulletin		N				N/A to Fit
	C1B-024.1	Throttle Control Restriction		N	43632.0			Inspection
	C1B-025	Installation of Single Wheel Ground Handling Wheel Locking Device		N				N/A to Fit
	C1B-026	Landing Gear Skid Tube Aft Sleeve Inspection		N				N/A to S/No
	C1B-027	Fuel Strainer Leak Check		N				N/A to S/No



Date
14/11/2019

Aircraft Status

G-CEOY

Type Schweizer 269C-1

Serial no 234

Total time 2648

NT Aviation

UK.145.01260 UK.MG.0632

Maintenance Program

MP/04444/P

AD Number	SB Number	Description	Recurring?	Interval	Last Complied with	Next Due	Time Remaining	Notes
		SBS						
2010-0129	C1B-028	Modification of Cabin Door Hinges	N		30/11/2011			Modification
	C1B-029	Incorrect Grease Identification in Certain Serial Number Helicopters						N/A by S/No
	C1B-030	Center Control Cover Contacting Lateral Cyclic Control Rod	N		30/11/2011			Inspection
	C1B-031	Incorrect Bushing used in 269C-1 Flight Controls	N		16/06/2019			Inspection
2011-12-16	C1B-032.1	Inspection and Modification of Tailboom Support Strut Adjustable Diameter Bolt	N		30/11/2011			Modification
	C1B-033	Clevis Pin Chaffing Bottom of Fuel Tank	N		30/11/2011			Inspection
	C1B-034	Inspection of Main Rotor Drive Thrust Bearing Journal Radius	N		30/11/2011			Inspection
	C1B-035	DRIVE TRAIN - Tail Rotor Drive Shaft Splined Fittings – Perform a One-Time Inspection and Implement a Recurring Inspection for Wear	N					N/A by S/No
2015-23-01	C1B-036	Tail Rotor Drive Shaft Splined Fittings Inspection	Y	100	2639.4	2739.4	91.4	Inspection
	C1B-037	One-Time Inspection to Remove from Service Engine and/or Rotor Tachometer Cables with a Hexagonal Connector on One End	N					N/A By Fit
	C1B-039	One-Time Tail Rotor (T/R) Blade Borescope Inspection for Excess Primer	N					N/A by S/No of Blades

